






Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 1 of 9



**FIG. 1a**




**FIG. 1b**




**FIG. 1c**




Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 2 of 9





**FIG. 2a**




**FIG. 2b**




**FIG. 2c**




**FIG. 3a**




**FIG. 3b**




**FIG. 3c**




Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 4 of 9




**FIG. 4a**



**FIG. 4b**




**FIG. 4c**




**FIG. 4d**




Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 5 of 9



**FIG. 5a**




**FIG. 5b**




**FIG. 5c**




Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 6 of 9




*FIG. 6c*




*FIG. 6b*




*FIG. 6a*



Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 7 of 9




**FIG. 7a**




**FIG. 7b**



Docket No. S1436.70001US00  
Applicant: Abang Ali, et al.  
Serial No. 09/834,187  
Filed: April 12, 2001  
For: Interlocking Mortarless Load  
Bearing Building Block System  
Replacement Sheet 8 of 9





**FIG. 7c**




**FIG. 7d**






**FIG. 8a**



**FIG. 8b**



**FIG. 8c**